


## heba EE - Gummihohlfeder Typ HC

Qualität
<u>w</u> eich = w
<u>m</u> ittel = m
<u>h</u> art = h



D	d	H
20	11	25
75	40	55
75	40	70
80	35	100
92	30	125
95	36	130
100	18	63
100	20	75
100	30	100
100	40	120
100	40	125
100	50	70
120	40	90
120	40	120
125	36	130


D	d	H
125	50	125
126	21	135
130	40	130
140	25	150
140	30	120
140	40	150
140	45	120
150	30	200
150	40	125
150	50	80
152	76	152
160	35	160
160	40	125
160	70	100
170	70	110

Technische Änderungen vorbehalten

Andere Kernauführungen, Sondergrößen und Elastomerqualitäten / -härten bitte anfragen.

## heba EE - Gummihohlfeder Typ HC

Qualität
<u>w</u> eich = w
<u>m</u> ittel = m
<u>h</u> art = h



D	d	H
170	80	150
175	40	125
180	60	220
180	70	100
180	85	100
200	36	130
200	48	115
200	65	175
200	68	180
200	70	100
200	70	110
200	70	125
200	70	175
200	70	180
200	70	260

D	d	H
200	90	200
200	100	160
220	60	160
220	70	250
230	60	200
240	60	250
240	70	100
240	70	220
240	70	250
248	20	248
250	52	130
250	60	250
250	70	100
250	70	250
250	85	104

Technische Änderungen vorbehalten

Andere Kernaussführungen, Sondergrößen und Elastomerqualitäten / -härten bitte anfragen.